

# BM Leibrandt Restoration Cape Pty Ltd(Knysna)

7 Wally Van Der Walt Street, The Island, Sedgefield, South Africa

## Job Card

Reference No:

20 Nov 2024

Claim Details			
Insurance Company	ABSA Insurance Company Limited	Claim No	520211
Department	ABSA HOC	Claims Handler	admin
Section	Building	Peril	Burst Pipes
Is Valid Claim	Uncertain	Damage Type	
VAT Number		Insured	DAVEL
Incident Description	Municipality sewerage pipe leaking, its cause damages to the drive way, sink hole next to the house.		
Excess Payable to Service Provider	R 1 000.00		

Contact Details			
Client Name	DAVEL	Client Cell	
Client Work	0826688373	Client Home	0826688373
Client Email	noeleendavel@gmail.com		
Risk Address	,109 MILKWOOD DRIVE, #, KNYSNA, 6571, SOUTH AFRICA		
ClaimsTech Name		ClaimTech Cell	
ClaimsTech Email			

### Claimed Items

Item No	Description	UOM	Quantity
---------	-------------	-----	----------

Client name and Surname:  
(Please print)

Client Signature:

Date:

### Excess Reiteration

Kindly note that the excess is payable by the insured before any work is carried out.

### Furniture removal

The service provider is not liable for any removal of furniture. Should the service provider be requested to remove any furniture, the insured must sign an indemnity form.

### Clearance certificate

Upon completion of repairs the insured must complete the service questionnaire and rate the level of service rendered by the service provider.

Only the insured/persons appointed by the insured can sign the clearance certificate